

## ORIGINAL EQUIPMENT TORQUE SENSOR



TransTec® Number **ETSM15016** is now available.

MAKE	MODEL	LH/RH DRIVE	MARKET	YEARS
CHEVROLET	MALIBU	LH	NORTH AMERICA	2006-2012

### Features and Benefits

- Original equipment replacement torque sensor for the column mount EPS unit on the above vehicle. Use TransTec® kit 8997 to rebuild the manual rack & pinion.
- This torque sensor can be identified by the gray heat shrink wrap covering the communication cable.

**ETSM15016** is in stock and ready for immediate shipment.

Call your Freudenberg-NOK customer service representative to place an order today!

a brand of

**FREUDENBERG-NOK**