

Bulletin

Application: Toyota A340E/F, A343F 2000-Up
Subject: Revised Planetary Thrust Washers

TB2 1/03

Toyota modified the output planetary carrier slightly to allow for improved lube distribution to the pinion gear shafts. This change affects the carrier assembly, upper thrust washer, and the lower thrust washer. The new washer has 5 locating tangs, compared to 2 on the previous washer. In addition, the revised washer has 5 lube channels, compared to 4 in the previous design.

Updated washers have been added to TransTec kits for the 2000-up A340E/F and A343F.

