


## ORIGINAL EQUIPMENT TORQUE SENSOR



Now available TransTec® Number **ETSM15006**

MAKE	MODEL	LH/RH DRIVE	MARKET	YEARS
FORD	ESCAPE	LH	NORTH AMERICA AND SOUTH AMERICA	06/04/09 - 2012
MERCURY	MARINER	LH	NORTH AMERICA AND SOUTH AMERICA	06/04/09 - 2011

### Features and Benefits

- Original equipment replacement torque sensor for the column mount EPS unit on the above vehicles. Use TransTec® kit 80R002 to rebuild manual rack & pinion.
- The torque sensor can be identified by the yellow heat shrink covering the communication cable.

**ETSM15006** is in stock and ready for immediate shipment

Call your Freudenberg-NOK customer service representative to place an order today!

a brand of

**FREUDENBERG-NOK**