

## Bulletin

**Application:** General Motors 4T65E 1997-Up  
**Subject:** Upper Channel Plate Gasket – 2<sup>nd</sup> Revision

TB12 8/03

General Motors has again altered the upper channel plate gasket for the 4T65E. The latest revision, GM's 3<sup>rd</sup> design, will retrofit all models from 1997-up.

The 2<sup>nd</sup> design (1<sup>st</sup> revision) gasket had an opening eliminated to aid in avoiding potential gasket blowouts (see illustration). Unfortunately, this created more concerns of gaskets blown out due to excessive pressure.

GM engineering has now added two slots to improve fluid flow. This is a running change at General Motors, and the new gasket will replace all previous gaskets for all models in TransTec kits with a date code of **G03** and later.

