

Application: 4T65E

Subject: BONDED VALVE BODY SEPARATOR PLATE

The valve body plate and gaskets for the 4T65E has always been a three piece design since its inception in 1997.

In 2003, General Motors started producing a bonded valve body plate that would service all 4T65E's from 1997-2003 under OEM # 24217552. In the 2004 model year, GM produced a new plate under OEM# 24224544 to service the 2004 models.

The current gaskets offered in our gasket and overhaul kits will work from 1997 to 2004.

Experience has shown that the gaskets on the bonded plates can be removed by various methods such as using a gasket remover produced by Permatex® or by submersing the plate in the heated water found in the sump of the parts cleaning machine (spray cabinet) for a couple of hours.

These bonded plates are proprietary to GM and are not available to the aftermarket. They must be ordered through your local dealership.

