


## ORIGINAL EQUIPMENT TORQUE SENSOR



TransTec® Number **ETSM15015** is now available.

MAKE	MODEL	ENGINE	MARKET	YEARS
FIAT	500	1.4 L	GLOBAL	2012-2014
FIAT	PANDA (169)	1.1	EUROPEAN	2004-2012
FIAT	PANDA (169)	1.2	EUROPEAN	2004-2012
FIAT	PANDA (169)	1.3 D MULTIJET	EUROPEAN	2004-2012
FIAT	PANDA (169)	1.3 D MULTIJET 4X4	EUROPEAN	2005-2012
FIAT	PANDA (169)	1.2 4X4	EUROPEAN	2005-2012
FIAT	PANDA (169)	1.4	EUROPEAN	2007-2012
FIAT	PANDA (169)	1.2 BI-POWER / NATURAL POWER	EUROPEAN	2007-2012
FIAT	PANDA (169)	1.3 D MULTIJET	EUROPEAN	2006-2012
FIAT	PANDA VAN (169)	1.2 4X4	EUROPEAN	2005-2012
FIAT	PANDA VAN (169)	1.2	EUROPEAN	2005-2012
FIAT	PANDA VAN (169)	1.3 JTD	EUROPEAN	2006-2012
FIAT	PANDA VAN (169)	1.3 JTD	EUROPEAN	2004-2012
LANCIA	YPSILON (843)	1.2	EUROPEAN	2004-2011
LANCIA	YPSILON (843)	1.2	EUROPEAN	2004-2011
LANCIA	YPSILON (843)	1.4 16V	EUROPEAN	2004-2011
LANCIA	YPSILON (843)	1.3 JTD	EUROPEAN	2004-2011
LANCIA	YPSILON (843)	1.4	EUROPEAN	2006-2011
LANCIA	YPSILON (843)	1.3 D MULTIJET	EUROPEAN	2007-2011
LANCIA	YPSILON (843)	1.3 D MULTIJET	EUROPEAN	2007-2011
LANCIA	YPSILON (843)	1.3 D MULTIJET	EUROPEAN	2007-2011

### Features and Benefits

- Original equipment replacement torque sensor for the column mount EPS unit on the above vehicles. Use TransTec® kit 80R007 to rebuild the manual rack & pinion.
- The torque sensor can be identified by the green heat shrink covering the communication cable.

**ETSM15015** is in stock and ready for immediate shipment

Call your Freudenberg-NOK customer service representative to place an order today!

a brand of

**FREUDENBERG-NOK**